


- CONNECTIONS:
1. CONNECT TEMPERATURE SENSOR WIRE ASSEMBLY TO J12. ATTACH TEMPERATURE SENSOR INSIDE REFRIGERATION UNIT.
  2. CONNECT COMPRESSOR POSITIVE (RED) TO J11 TERMINAL 1
  3. CONNECT COMPRESSOR NEGATIVE (BLACK) TO J11 TERMINAL 2 (SEE NOTE 1)
  4. CONNECT HEATER POSITIVE (RED) TO J10 TERMINAL 1
  5. CONNECT HEATER NEGATIVE (BLACK) TO J10 TERMINAL 2 (SEE NOTE 1)
  6. CONNECT +12VOLT DC SUPPLY TO RED WIRE GOING TO THE 8 AMP FUSE HOLDER (USE WIRE NUT)
  7. CONNECT GROUND TO BLACK WIRE GOING TO J8 (USE WIRE NUT)



THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF SINGLETEC, INC. ANY REPRODUCTION IN PART OR WHOLE WITHOUT THE WRITTEN PERMISSION OF SINGLETEC, INC. IS PROHIBITED.		SINGLETEC, INC.	
DATE 11/19/2004		CUSTOMER WIRING DRAWING	
DRAWN KCH	SIZE	DWG NO. S099-017	REV
SCALE NOT TO SCALE		SHEET 1	OF 1